



Construction conditions in Loviisa, Finland

- Very good construction conditions
- Good construction conditions
- Demanding construction conditions
- Very demanding construction conditions
- Bedrock outcrop
- Fill material
- Constructed area
- Surface water

Map based on:
 Superficial deposits mapping of Finland 1 : 200 000 © Geological Survey of Finland
 Digital elevation model 25m © National Land Survey of Finland 2013
 Contains 03/2013 data from the Topographic Database
 of the National Land Survey of Finland © NLS and HALTIK